19

Corner Record - Douglas County, Nevada

When recorded, return a copy to:

USFS, LTBMU, Lands Dept.

✓ 35 College Dr.

South Lake Tahoe, CA 96150

DOC # 0770112
09/09/2010 02:53 PM Deputy: SG
OFFICIAL RECORD
Requested By:
U S FOREST SERVICE

Douglas County - NV Karen Ellison - Recorder

Page: 1 Of 2 Fee: 15.00 BK-0910 PG-1803 RPTT: 0.00



## Surveyor's Certificate

- I, <u>Mary Niederberger-Lee</u>, a Professional Land Surveyor registered in the state of Nevada, certify that:
  - 1. This corner record represents the establishment of restoration of a corner or accessory to a corner conducted under my direct supervision.
  - 2. The monument or accessories perpetuated lie within the section and township/range printed on the map, and the establishment or restoration was completed on the date printed on the map.
  - 3. This corner record has been filed pursuant to NRS 329.140 or 329.150 and complies with the provision of NAC 329.101 and any local ordinances in effect on the date the establishment or restoration was completed
  - 4. The monument or witness monument and accessories found are of the character shown, occupy the positions indicated and are of sufficient durability.



Exp. 12/31/2011

Mary Niederberger-Lee, PLS 11320

Date Signed

BK- 0910 PG- 1804 2 09/09/2010

Corner Record Date of Survey: APN: 1318-15-610-007 & -510-001 June 29, 2010 310 Ute Way, 308 Ute Way Lot 7 & 8, Block C Filed as required by the Statues of Round Hill Village #2, Doc #30185 Nevada, 1969, Chapter 329 \$15 T13N R18E M.D.M. **PVT** 2 (S4°12'57"E 8 **USA** 168.00) (S3°01'31"E 164.00") \$3°05'16"E 164.08 3 Singan 808 Mestabe 13.00 6 7 USA See 4147 882 (S13°07'47"E LC=35.98'(c)) (r=225.00)(S83°49'02"E 154.69") S80°21'26"E 87.72' (S17°42'57"E 27.00') (S80°21'26"E LC=87.72'(c)). (r=200.00) Basis of bearing (N63°06'00 W 86.00) (N27°16'36"E) (\$85°24'31"E LC=94.90'(c)) (LC=28.29' (c)) N65°23'40"W LC=16.02 -(r=20.00') (r=125.00) (S72°17'00"W 18.00") (N65°23'40"W LC=16.02'(c)) (r=200.00')N63°06'00"W 14.00'--(N63°06'00"W 14.00") • Set 5/8" rebar/topper (LS 11320) 0 Found rebar/topper (RLS 2280) Found rebar no tag Found plugged pipe (PLS 3519) 0 nothing found, nothing set record bearing and distance from sub'd map () calculated bearing and distance from sub'd map (c)